


REPORT

TRUESDAIL LABORATORIES, INC.



14201 FRANKLIN AVENUE
TUSTIN, CALIFORNIA 92680
AREA CODE 714 • 730-6239
AREA CODE 213 • 225-1564
CABLE: TRU ELABS

CHEMISTS - MICROBIOLOGISTS - ENGINEERS
RESEARCH - DEVELOPMENT - TESTING

CLIENT DOUGLAS AIRCRAFT COMPANY
Internal Mail Code 211-40
3855 Lakewood Boulevard
Long Beach, CA 90846

DATE September 27, 1988

RECEIVED September 20, 1988

SAMPLE Monthly Storm Drain Inspection
(September, 1988)
P.O. No.: # T & M-23465-C

LABORATORY NO. 30868/30869


INVESTIGATION

As requested by the CRWQCB for NPDES permit numbers CA0001406
and CA0001414

RESULTS

A representative of Truesdail Laboratories, Inc. tested the storm drain discharge on September 20, 1988 at the Douglas, Long Beach (003) and Torrance facilities. The discharge was tested for flow rate, pH, and temperature. The results are as follows:

<u>Sample I.D.</u>	<u>Date</u>	<u>Time</u>	<u>Flow-gpd</u>	<u>Temp OF</u>	<u>pH Units</u>
Long Beach (003)	9-20-88	3:00	153,446	72	8.0
Torrance	9-20-88	12:25	3,773	74	7.6



Respectfully submitted,
TRUESDAIL LABORATORIES, INC.

Luis Perez, Supervisor
Industrial Waste

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.